

Water Quality Noncompliance Notification

See back of Form for Guidance for Completion

Unauthorized Discharge

Reportable Effluent Violation

Other

General Information

Entity Name: Trophy Club Municipal Utility District No. 1

Telephone No (#####): (682) 813-4600

Permittee

TCEQ Region: R4 - DFW

County: Denton

*Permit Number: TX0055735

Subscriber

Noncompliance Summary

Description and Cause of Noncompliance (include location, discharge route, and estimated volume of unauthorized discharge):

On February 17th 2021 we had an SSO at L/S #2, located on TW King behind 4 Edgemere Ct. It was due a power outage caused by the rolling blackouts. We arrived onsite just before overflow started. In the time it took us to hook up the generator and begin pumping down Lift Station #2 we estimated that 438-Gallons had overflowed. After pumping down the lift station we cleaned-up the affected area from any dubris and disinfected the affected area with Clear Mint.

Duration:

Start Date: 2/17/2021

End Date: 2/17/21

Or

Date Expected to be Corrected: 2/17/2021

Time: 2:45 pm

Time: 2:53 pm

Potential Danger to Human Health and Safety or the Environment:

None

Actions Taken

Monitoring Data: Data should be attached or submitted to TCEQ when available.

Field Measurements

Laboratory Samples

Fish Kill (If yes, estimated number killed):

Yes No

Yes No

Yes No

Actions Taken to Mitigate Adverse Effects:

Cleaned up all dubris and disinfected the affected area with Clear Mint.

Actions Taken to Correct the Problem and Prevent Recurrence:


We have the portable generator on fueled and ready to go as we are monitoring the Wastewater Treatment Plant and all Lift Stations 24-Hours a day until we are notified that the power is fully restored.

Verification Information

Information Reported By (Name/Title): Frank Isola / WW-Supervisor

Date Reported: Feb 17, 2021

Signature:



Note: If this form is being used for a 5-day written report, a copy of the form should be sent to the TCEQ Region Office, and the original to: TCEQ, Compliance Monitoring Team (MC224), Enforcement Division, P.O. Box 13087, Austin, TX 78711-3087.

* If the noncompliance is an unauthorized discharge from a wastewater collection system, use the permit number of the treatment plant to which the collection system is tied. If you are uncertain of this permit number, you may call the TCEQ Regional Office for assistance.